



15708 Pomerado Road, Suite N208, Poway, CA 92064

May 14, 2018

Notice of Recall: Arm Restraints Manufactured and Certified to SFI Specification 3.3 by RJS and equipped with snap-clasp tethers.

To All Racers, Sanctioning Body Officials, Equipment Wholesalers and Retailers,

Arm Restraints Manufactured and Certified to SFI Specification 3.3 by RJS and equipped with snap-clasp type tethers have been found to be non-compliant with SFI Specification 3.3. All snap-clasp type Arm Restraint Assemblies Manufactured and Certified to SFI Specification 3.3 by RJS must be immediately be removed from service and returned to RJS, per the attached notice from RJS.

This recall only includes RJS Arm Restraints with snap-clasp tethers. RJS Arm restraints with double "D" ring tether attachments are not affected by this recall.

IMPORTANT SAFETY RECALL



***RECALL ISSUED ON PART NUMBERS:
11000301, 11000303, 11000304, 11000305,
11000306, 11000307, 11000308,
11000310, 11000313
WITH SNAP CLASP***



**RJS WILL REPLACE AT OUR
EXPENSE FOR DOUBLE D RING
STYLE ARM RESTRAINTS.
FOR MORE INFORMATION
PLEASE CONTACT
STEVE@RJSRACING.COM
OR CALL 844-904-RACE [7223]**

